Scope of V	Nork for Property	Located a	ıt:		2347 North 17th Street				
	Property is: Sin	gle Family	1	Duplex	□ Other □				
Date:	10/28/2016								
take no respons		ered after the	inspec	tion date, o	r for omissions throug	the Redevelopment Authority, and the Redevelopment Authority, and the Redevelopment of the Redevelopment Authority, and the Redevelopment Authority and			
Exterior C	ondition Report								
Location Site	Required Work Landscaping	n/a	a 🔽	Yes 🗌	Note/Comments	3	\$	Cost	
	Steps/Handrails	n/a	a 🗹	Yes 🗌			\$		
	Service walks	n/a	a 🔲	Yes 🗸			\$	2,500.00	
	Fencing	n/a	a 🗌	Yes 🗸			\$	750.00	
	Parking	n/a	a 🔲	Yes 🗸			\$	4,000.00	
	Retaining walls	n/a	a 🔽	Yes 🗌			\$		
	Other	n/a	a 🔲	Yes 🗆			\$		
	Other	n/a	a 🗆	Yes 🗌			\$		
Garage	Singles: repair	n/a	a 🗌	Yes 🗌			\$		
	Shingles: Roof over e	xisting n/a	a 🗌	Yes 🗌			\$		
	Shingles:Tear off & re	roof n/a	a 🗌	Yes 🗌			\$		
	Gutters/downspouts	n/a	a 🗌	Yes 🗌			\$		
	Flashing	n/a	a 🗌	Yes 🗌			\$		
	Eaves	n/a	a 🗌	Yes 🗌			\$		
	Siding	n/a	a _ 🗌	Yes 🗌			\$		
	Doors	n/a	a 🔲	Yes 🗌		_	\$		
	Windows	n/a	a 🗌	Yes 🗌			\$		
	Slab	n/a	a 🗌	Yes 🗌			\$		
	Paint	n/a	a 🗌	Yes 🗌			\$		
	Electrical	n/a	a 🗆	Yes 🗌			\$		
	Other	n/a	a 🗆	Yes 🗌			\$		
Porches	Roof	n/a	a 🗸	Yes 🗌			\$		
	Rear porch steps	n/a	a 🔲	Yes 🗸	replace or repair l	both	\$	2,500.00	
	Decklower	n/a	a 🗌	Yes 🗸	on front porch		\$	200.00	
	Steps/handrails	n/a	a 🔽	Yes 🗌			\$		
	Ceiling	n/a	a 🔽	Yes 🗌			\$		
	Guardrails	n/a	a	Yes 🗹	on front porch		\$	250.00	
	Structural	n/a	a 🗸	Yes			\$		
	Paint	n/a	a 🗌	Yes 🗸			\$	750.00	

n/a Yes

\$

Other

House

Chimney	n/a ☑	Yes 🗌		\$
Shingles: repair	n/a ✓	Yes 🗌		\$
Shingles: Roof over existing	n/a ✓	Yes 🗌		\$
Shingles:Tear off & re-roof	n/a 🗌	Yes 🗸		\$ 9,500.00
Gutters/downspouts	n/a 🗌	Yes 🗸		\$ 1,050.00
Flashing	n/a 🗌	Yes 🗸		\$ 300.00
Eaves	n/a _✓	Yes 🗌		\$
Siding	n/a 🔲	Yes 🗸		\$ 1,250.00
Storm Doors	n/a 🔽	Yes 🗌		\$
Prime ("main") Doors	n/a ✓	Yes 🗌		\$
Storm Windows	n/a ✓	Yes 🗌		\$
Prime ("main") Windows	n/a ✓	Yes 🗌		\$
Paint	n/a 🗌	Yes 🗸		\$ 2,500.00
Foundation	n/a 🔽	Yes 🗌		\$
Electrical	n/a ✓	Yes 🗌		\$
Other	n/a	Yes 🗸	return to single family occupancy - remove illegal	3,000.00
			2nd floor unit	\$
Other	n/a 🗌	Yes 🗌		\$
Other	n/a 🗌	Yes 🗌		\$
Other	n/a 🗌	Yes 🗌		\$

Exterior: Estimated Cost:*

\$

28,550.00

^{*}average contracted cost. Actual costs may vary. Self help will reduce the amount.

interior Cor	nation Report				Lauran mail of dumlars		
	Unit: Entire unit (single family) Upper unit of duplex				Lower unit of duplex Other		
Mechanical	Required Work						
Heating	December 1997	-/- 🗔	Voo			Φ.	
	Repair/replace boiler	n/a ✓	Yes	<u>⊔</u>	-	\$	
	Repair radiation	n/a ✓	Yes		<u></u>	\$	
	Repair/replace furnace	n/a ☑	Yes			\$	
	Repair ductwork	n/a ✓	Yes			\$	
	Replace thermostat	n/a 🗸	Yes		_	\$	
	Repair/replace grilles	n/a ✓	Yes		-	\$	
	Tune boiler/furn. insp ht exchang	j∉n/a □	Yes	1		\$	325.00
Electrical	Repair/replace receptacles	n/a 🔲	Yes	7	open junction boxes in basement	\$	250.00
	Repair/replace switches	n/a ✓	Yes			\$	
	Repair/replace fixtures	n/a 🗸	Yes		7	\$	
	Install outlets and circuits	n/a 🗸	Yes			\$	
	Install outlets and circuits	n/a 🗸	Yes			\$	
	Install outlets and circuits	n/a 🗸	Yes			\$	
	Install outlets and circuits	n/a 🗸	Yes			\$	
	Upgrade service	n/a 🗸	Yes			\$	
	Other	n/a \square	Yes	П		\$	
	Other	n/a \square	Yes			\$	
Plumbing	01101	174			_	Ψ	
	Repair/replace kitchen sink	n/a ✓	Yes			\$	
	Repair/replace kitchen sink fauce	e n/a 🔽	Yes			\$	
	Repair/replace tub	n/a 🗌	Yes			\$	
	Repair/replace tub faucet	n/a 🔲	Yes			\$	
	Repair/replace toilet	n/a 🗌	Yes	1	2nd floor bathroom	\$	2,500.00
	Repair/replace lavatory	n/a 🗌	Yes			\$	
	Repair/replace lavatory faucet	n/a 🗌	Yes			\$	
	Repair/replace wash tub	n/a 🗸	Yes			\$	
	Repair/replace wash tub faucet	n/a ✓	Yes			\$	
	Unclog piping:	n/a 🗸	Yes			\$	
	Repair drain/waste/vent piping	n/a ☑	Yes		_	\$	
	Repair water piping	n/a ✓	Yes			\$	
	Repair/replace water heater	n/a ✓	Yes		_	\$	
	Other	n/a 🗆	Yes	П		 \$	
	- Cu 161	11/a 📙	1 63	<u> </u>	_	Ψ	

n/a Yes

Other

\$

Windows							
	Replace broken glass	n/a [Yes	√	basement window	\$ 250.00
D	Repair or replace sash	n/a [4	Yes		-	\$
Doors	Repair or replace doors	n/a [√	Yes			\$
	Repair or repl. locks/latches	n/a [√	Yes		Self Help	\$
Walls/Ceilings	Repair or repl. @ defective	n/a [1	Yes		_	\$
Paint	Repair or repl. @ defective	n/a [7	Yes			\$
Fire Safety	Install smoke/CO alarm:bsmt.	n/a [7	Yes	П	Self Help	\$
	Install smoke/CO alarm: 1st flr.			Yes		Self Help	\$
llandraila	Install smoke/CO alarm: 2nd flr.	n/a [4	Yes		Self Help	\$
Handrails	Repair/replace defective	n/a _[Yes	7	_	\$ 250.00
Stairs	Repair defective	n/a [Yes	7		\$ 2,100.00
Floors	Repair defective	n/a [4	Yes			\$
Other		n/a [Yes			\$
		n/a [Yes			\$
		n/a [Yes			\$
		n/a _[Yes		_	\$
						Interior: Estimated Cost:	\$ 5,675.00
						Total Exterior and Interior Cost:*	\$ 34,225.00

Inspected by: Jeff Sporer Date: 10/27/2016

Self Help

Work listed as "self help" means the cost estimate includes only the cost of the materials, not labor or equipment.

Important Information Regarding Permits

All plumbing, heating, electrical, and structural repairs require permits before work can start. Permits are also required for other work such as new siding, new drywall, new doors. Permits are obtained at the Development Center located on the first floor of 809 N. Broadway.

Licensed contractors must do the above work, although owner occupants may be eligible to do maintenance work and structural/carpentry repairs.

Owner occupants may be eligible to do plumbing work on the unit they live in, but check with the plumbing inspector first.

Generally, minor carpentry repairs, plaster patching, and painting do not require permits.

Anyone disturbing painted surfaces must assume they contain lead paint if the home was built before 1978. Contractors must be licensed to do lead abatement and must obtain a permit. Permits are obtained from the Health Department, located at 7630 W. Mill Road.

^{*}average contracted cost. Actual costs may vary. Self help will reduce the amount.